IMPROVEMENT ORDER



Venue	Date	Time Attack Ref No.
Brands Hatch	16 th June 2024	N/A
Driver/Entrant Scott Parkin	Competition No. 17 (217)	Chassis I.D Number/ class Club Pro

The following items do not comply with the current Championship Regulations and MUST be rectified before the date or time shown below

No.	Description of Improvement Required	Regulation & Page No.
1	Carbon rear doors need windows and any windows replaced with clear polycarbonate must be not less than 4mm thick	5.1 page 10 and 5.6.2 page 12.
2	Front bonnet open must have a mesh over it and the front and rear wheels / tires must not be visible from behind above 100mm from the center of the wheels.	5.6.1 page 12 and 5.6.5 page 13

Rectification Required Before:

Round 5, Oulton Park 20th July 2024

Cham	nionshi	p Scrutineer
VIIAIII	PIUIISIII	y Sciulineer

Name:

Michael Mattison Signature:

Date & Time:

16th June 2024